




# テストバー

- ・高精度
- ・JQA検査書付き



呼び	L	D	M
MT0	100	12	M15 × 1
1			
2	175	24	M27 × 1
3	235	32	M36 × 1.5
4	335	40	M48 × 1.5
5			
6		63	
NT30W	235	32	
40U	335	40	
45U		63	
50U			
BT30	200	30	
BT40	300	40	
BT50		50	